

ATTACHMENT A1
BLAST DAMAGE ASSESSMENT OF PIT WALLS

BLAST DAMAGE ASSESSMENT – Hornsby Quarry – Northern Pit Slope

This system provides a basis for the qualitative geotechnical assessment of blast damage to pit walls. The assessment is based on commonly observed features. Highlighted features are present in the wall.

| Number | Classification | Typical Features Observed |
|---------------|-----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | None | <ul style="list-style-type: none"> • blast holes visible • scars of excavation or shovel both evident on face • presplit holes readily evident on face • no displacement on joints • generally no further excavation possible |
| 2. | Slight | <ul style="list-style-type: none"> • blast holes visible • horizontal cracking evident immediately below bench crest • minor displacement of upper blocks • radial cracks evident in blast or presplit holes |
| 3. | Moderate | <ul style="list-style-type: none"> • major subhorizontal cracking evident immediately below bench crest • displacement of up to 50 mm evident across some joints • in closely jointed rocks the upper rock mass is extensively loosened • most joints open 1 to 10 mm • some loss of bench crest 1 to 3m |
| 4. | Severe | <ul style="list-style-type: none"> • no blast holes visible • blast induces crushing or fines evident • rock mass extensively loosened • rock blocks dislocated or reoriented • extensive break back of berm crest, generally greater than the 2m • most joints open 5 to 20 mm |

OVERALL ASSESSMENT: MODERATE TO SEVERE

BLAST DAMAGE ASSESSMENT – Hornsby Quarry – Eastern Pit Slope

This system provides a basis for the qualitative geotechnical assessment of blast damage to pit walls. The assessment is based on commonly observed features. Highlighted features are present in the wall.

| Number | Classification | Typical Features Observed |
|---------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | None | <ul style="list-style-type: none"> • blast holes visible • scars of excavation or shovel both evident on face • presplit holes readily evident on face • no displacement on joints • generally no further excavation possible |
| 2. | Slight | <ul style="list-style-type: none"> • blast holes visible • horizontal cracking evident immediately below bench crest • minor displacement of upper blocks • radial cracks evident in blast or presplit holes |
| 3. | Moderate | <ul style="list-style-type: none"> • major subhorizontal cracking evident immediately below bench crest • displacement of up to 50 mm evident across some joints • in closely jointed rocks the upper rock mass is extensively loosened • most joints open 1 to 10 mm • some loss of bench crest 1 to 3m |
| 4. | Severe | <ul style="list-style-type: none"> • no blast holes visible • blast induces crushing or fines evident • rock mass extensively loosened • rock blocks dislocated or reoriented • extensive break back of berm crest, generally greater than the 2m • most joints open 5 to 20 mm |

OVERALL ASSESSMENT: MODERATE TO SEVERE

BLAST DAMAGE ASSESSMENT – Hornsby Quarry – Southern Pit Slope

This system provides a basis for the qualitative geotechnical assessment of blast damage to pit walls. The assessment is based on commonly observed features. Highlighted features are present in the wall.

| Number | Classification | Typical Features Observed |
|---------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | None | <ul style="list-style-type: none"> • blast holes visible • scars of excavation or shovel both evident on face • presplit holes readily evident on face • no displacement on joints • generally no further excavation possible |
| 2. | Slight | <ul style="list-style-type: none"> • blast holes visible • horizontal cracking evident immediately below bench crest • minor displacement of upper blocks • radial cracks evident in blast or presplit holes |
| 3. | Moderate | <ul style="list-style-type: none"> • major subhorizontal cracking evident immediately below bench crest • displacement of up to 50 mm evident across some joints • in closely jointed rocks the upper rock mass is extensively loosened • most joints open 1 to 10 mm • some loss of bench crest 1 to 3m |
| 4. | Severe | <ul style="list-style-type: none"> • no blast holes visible • blast induces crushing or fines evident • rock mass extensively loosened • rock blocks dislocated or reoriented • extensive break back of berm crest, generally greater than the 2m • most joints open 5 to 20 mm |

OVERALL ASSESSMENT: MODERATE TO SEVERE

BLAST DAMAGE ASSESSMENT – Hornsby Quarry – Western Pit Slope

This system provides a basis for the qualitative geotechnical assessment of blast damage to pit walls. The assessment is based on commonly observed features. Highlighted features are present in the wall.

| Number | Classification | Typical Features Observed |
|---------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | None | <ul style="list-style-type: none"> • blast holes visible • scars of excavation or shovel both evident on face • presplit holes readily evident on face • no displacement on joints • generally no further excavation possible |
| 2. | Slight | <ul style="list-style-type: none"> • blast holes visible • horizontal cracking evident immediately below bench crest • minor displacement of upper blocks • radial cracks evident in blast or presplit holes |
| 3. | Moderate | <ul style="list-style-type: none"> • major subhorizontal cracking evident immediately below bench crest • displacement of up to 50 mm evident across some joints • in closely jointed rocks the upper rock mass is extensively loosened • most joints open 1 to 10 mm • some loss of bench crest 1 to 3m |
| 4. | Severe | <ul style="list-style-type: none"> • no blast holes visible • blast induces crushing or fines evident • rock mass extensively loosened • rock blocks dislocated or reoriented • extensive break back of berm crest, generally greater than the 2m • most joints open 5 to 20 mm |

OVERALL ASSESSMENT: MODERATE TO SEVERE