





## NOTES:

- Existing shelter to be retained
- Tactiles positioned in accordance with AS/ NZS 1428.4.1 to adhere with DDA compliance (Refer Scenario 4).
- 3. Fall no more than 2.5%
- Excavate and pour new concrete to surrounding areas to have a smooth transition.
- Reinstate all disturbed areas to match existing, refer hatch legend.

## NOTE:

EXISTING CONFIG - AD STATIC PROPOSED CONFIG - AD STATIC

SURVEY		TRANSITION	TRANSITION TABLE	
$\Lambda$	<b>↓ 4.0</b>			
<u> </u>	<b>↓ 4.0</b>			
3	ightarrow 3.2			



GRASS

NEW PAVERS/CONCRETE





SITE ADDRESS: PACIFIC HIGHWAY W/O JERSEY ST NORTH S/S, ASQUITH

SITE # : 20464 BUS STOP: 207731



)				SCALE	DRAWING NO.
į				1:70	. 102
	В	21/10/20	AL	REV NO.	DATE
	Α	20/04/17	AC		
-	REV.	DATE	INT.	В	21/10/20